



Release Note

Software Version: 2.12.20

Models: X3SW/X3S (P) Lite/X3S (P) Pro/X3SGPro/X3SGLite/X3UPro

Date: 2024.7.29



Content

Content	2
1 Revise History	3
2 Release 2.12.20	4
2.1 New Features	4
2.2 Improvement	4
2.3 Bug Fix	5
2.4 New Features Description	5
3 Release 2.4.13.x	6
3.1 Optimization	6
4 Release 2.4.12.5	7
4.1 New Features	7
4.2 Optimization	7
4.3 Bug Fix	7
5 Release 2.4.X	9
5.1 Optimization	9
6 Release 2.4.10.1	10
6.1 New Features	10
6.2 Bug Fix	10

1 Revise History

No.	Version	Release Time
1	2.4.10.1	2022.1.7
2	2.4.X	2022.8.24
3	2.4.12.5	2023.2.13
4	2.4.13.x	2023.11.17
5	2.12.20	2024.7.29

2 Release 2.12.20

Models	Software Version	Comment
X3SW/X3S(P)Lite/X3S(P)Pro/X3S GPro/X3SGLite/X3UPro	2.12.20	

2.1 New Features

1. Add support for Chinese input method on new phones
2. Add display of device SN information on the web page
3. Add Kazakh language support on the phone
4. Add Persian language support on the phone

2.2 Improvement

1. Optimize Russian translation
2. Optimize German translation
3. Optimize French call time format
4. Optimize display of Russian call records
5. Optimize the feature for enabling the voicemail and support configuring voicemail numbers
6. Optimize the IP address input interface to address sequential issues under the 123 input method
7. Optimize the display issue in the upper left corner of unregistered standby mode
8. Optimize sending the hostname to the DHCP server via DHCP Option 12

2.3 Bug Fix

1. Fix the issue with LED flashing after viewing missed calls when the Miss Call Icon is enabled
2. Fix the issue where contacts cannot be dialed using the directional keys
3. Fix issues related to group ringing

2.4 New Features Description

1. Add Support for Chinese Input Method on the Phone

Feature Description: Support for Chinese input method on the phone.

Implementation Details:

Modify the phone's LCD language to Chinese or Traditional Chinese.

When selecting an editable field or creating a new message, the input method sequence should be: Abc, 2aB, Pinyin, 123, abc, ABC.

2. Add Device SN Information Display on Web Page

Feature Description: Display device SN (Serial Number) information on the web page.

Implementation Details:

Add a SN field to the web page to facilitate the use of SN for device management by certain systems.



3 Release 2.4.13.x

Models	Software Version	Comment
X3SW/X3S(P)Lite/X3S(P)Pro/X3S GPro/X3SGLite/X3UPro	2.4.13.x	

3.1 Optimization

1. Enhanced the TR069 functionality.
2. Improved the call waiting feature.

4 Release 2.4.12.5

Models	Software Version	Comment
X3SW/X3S(P)Lite/X3S(P)Pro/X3S GPro/X3SGLite/X3UPro	2.4.12.5	

4.1 New Features

3. Addition of Croatian
4. Add Japanese
5. Port SIP PBX Call Park Compatibility

4.2 Optimization

1. Optimizing DNS Query Mode
2. Optimization of French-language translation documents
3. Optimization of automated deployment-related issues
4. Optimize the time to return the Dsskey Home interface from other Dsskey interfaces
5. Optimize the phone to receive calls with Reason field from Cancele as received calls in the call log
6. Extended LDAP Server Address Word Limit

4.3 Bug Fix

1. Fix Phone Page Upgrade Dsskey Icon Help Message Error
2. Fix the problem that the LED light on the sub-screen of the phone does not change with the page number of the sub-screen

3. Fixing problems related to abnormalities in the use of Internet telephone books
4. Fix Unstable Phone Calls under WiFi
5. Fix the problem of sending STUN packets when STUN is turned off under special server
6. Fix the problem of delay in answering the call using the handle to set up the call

5 Release 2.4.X

Models	Software Version	Comment
X3SW/X3S (P) Lite/X3S (P) Pro/ X3SGPro/X3SGLite/X3UPro	2.4.X	

5.1 Optimization

1. Optimize translation issues related to contacts

6 Release 2.4.10.1

Models	Software Version	Comment
X3SW/X3S (P) Lite/X3S (P) Pro/ X3SGPro/X3SGLite/X3UPro	2.4.10.1	

6.1 New Features

1. IP Phone with color screen supports Caller ID Display
2. Add anti-degradation function to the phone
3. The phone supports setting startup logo image after it is upgraded on web page

6.2 Bug Fix

1. Fix the problem that the Wi-Fi MAC address displayed on the LCD of the phone does not match the actual Wi-Fi MAC address obtained by the phone

2. Fix the problem that the X3S Pro phone under the special server will prompt that the IP cannot be obtained after obtaining the address

3. Fix the problem that the screen displays a white screen after the phone upgrade version is completed under special circumstances