



Release Note

Software Version: 2.2.3

Models: X1SP/X3U/X3SG

Date: 2020.7.31



Content

Content	2
1 Revise History	3
2 Release 2.2.3	4
2.1 New Features.....	4
2.2 Optimization.....	4
2.3 Bug Fix.....	5
3 Release 2.0.1	6
3.1 New Features.....	6
3.2 Optimization.....	6
3.3 Bug Fix.....	7

1 Revise History

No.	Version	Release Time
1	2.0.1	2020.5.12
2	2.2.3	2020.7.31

2 Release 2.2.3

Models	Software Version	Comment
X1SP/X3U/X3SG	2.2.3	

2.1 New Features

1. Add default password modification prompt on Webpage
2. Add the Web page configuration to control time/date display
3. Sidekey display area can be set to three lengths of short, medium and long

2.2 Optimization

1. Improve the situation that the upgraded prompt message can be chosen to display
2. Optimize LDAP related content
3. Improve related content of IP address conflict
4. Fix the problem that hands-free adjustment of ring volume does not take effect when under the mode of headset group listening
5. Compatible with call park function of Metaswitch
6. Compatible with CTI function of Yeastar server

2.3 Bug Fix

1. Fixed the issue that the webpage prompts error when the two multicasts are switched the order
2. Fix the problem that there is no prompt to hang up the peer when attending the transfer
3. Fixed the problem that when the subscribed BLF has multiple incoming calls, the test phone will only displays the pick up of the first call
4. Fix the problem that the factory reset is stuck on the reboot interface
5. Fix the problem that dialing rules cannot be deleted and modified under some certain circumstances (X1SP)

3 Release 2.0.1

Models	Software Version	Comment
X1SP/X3U/X3SG	2.0.1	

3.1 New Features

4. Add Portuguese to Web page
5. Support customizable BLF setting

3.2 Optimization

1. Automatic certificate upgrade. Support package upgrade.
2. Optimize the display of UI front
6. Add the display of the last run time on Web
7. Add the IP conflict reminder on LCD
8. Add the configuration of Enable DTMF/Transfer/Hold/Conference on Web
9. Add the reminder of password modification when the registration password is default.

3.3 Bug Fix

6. Fix the issue of invalid webFliter after configuration
7. Fix the issue of IP phone crash when using the G.726 codec in communication under the special situation.
8. Fix the issue that the headphone is soundless when the call is answered automatically in group ring mode.
9. Fix the issue of the memory leak after multiple communications through uaCSTA.
10. Fix the abnormal issue of ptime setting.
11. Fix the issue that IP phone cannot receive IP address because of the wrong Vlan ID received through option132.
12. Fix the issue of abnormal issue of Networks after the phone has sent more than 2W data package in 30 seconds.
13. Fix the issue of no prompt when clicking the upload button with empty equipment certificate.
14. Fix the issue that dial query page does not support fuzzy query.
15. Fix the issue that dial pad cannot be light up after pressing the button of the base of EHS headphone.
16. Fix the issue that the call log cannot be deleted after resetting.